



20 bar
operating pressure

RAL 9005
standard colour

DESCRIPTION

Humidity indicator CHI has been designed for optical indication of dew point in compressed air system. Humidity / dew point is determined based on the colour of a silica gel, from orange (dry) to translucent (wet).

CHI can be used in variety of applications. For applications not listed please contact producer or your local distributor.

CHI

HUMIDITY INDICATOR



TECHNICAL DATA							
Operating pressure	0-20 bar _g			0-290 psi			
Total weight	375 g			0,83 lbs			
Adsorbent weight	75 g			0,66 lbs			
Typical installation	Head of filter housing						
Accuracy							
Air loss	Some compressed air is lost due to the operation of the indicator.						
	A	B	C	D	E	F	G
Dimensions (mm)	81	55	80	84	M5	24	57
Silicagel colour	Condition			Dew point			
Orange	Dry air			-25°C			
Translucent	Wet air			+15°C			

APPLICATIONS

- Desiccant dryers
- General compressed air

